

FIG. 1

09637-1




FIG. 2




FIG. 3




FIG. 4


[illegible]

FIG. 5

09863718.052304




FIG. 6

SECRET




FIG. 7

09863748.052304
T0E250"8T.2E9860




FIG. 8




FIG. 9




FIG. 10a




FIG. 10b




FIG. 11a




FIG. 11b




Fig. 12




Fig. 13

09863748-052304
T06250 BTZ59860






Fig. 14
DETAIL A
SCALE 2 : 1



SECTION B-B

Fig. 15



DETAIL D
SCALE 4 : 1

Fig. 16